

MD5: 69561850afc4a8cfaa31af7417c44462

[Source Version] V4.5R90F02, V4.5R90F02SP01, V4.5R90F02SP02 [Target Version] V4.5R90F02SP03 [Matching Versions of Collaborative Devices] ADS: V4.5R90F02, V4.5R90F02SP01, V4.5R90F02SP02, V4.5R90F02SP03

ADS M: V4.5R90F02SP03

TAT: V2.0.0 [Function Description]

1. The performance of the traffic collector is optimized.
2. Switches are added for top n statistics for traffic.
3. Third-party interfaces are optimized.
4. The API description document is updated.
5. Some bugs are fixed.

[Important Notes]

1. The web-based manager is inaccessible during system updating.
2. All engines are stopped during system updating.
3. After updating is complete, users need to refresh the web page as prompted.
4. During the upgrade, it is normal that the web-based manager displays an error message "502 Bad Gateway" or directly denies your access request. Please refresh the web-based manager 5 minutes later, and then check Product Version in About. If the version is V4.5R90F02SP03, the upgrade succeeds.