

[Version No.]

V4.5R90F02.sp06

[Source Version]

V4.5R90F02,V4.5R90F02.sp01,V4.5R90F02.sp01.C236,V4.5R90F02.sp01.C236.HD,V4.5R90F02.sp02,V4.5R90F02.sp03,V4.5R90F02.sp04,V4.5R90F02.sp05

[Target Version]

V4.5R90F02.sp06

[Matching Versions of Collaborative Devices]

NTA:

V4.5R90F02,V4.5R90F02.sp01,V4.5R90F02.sp02,V4.5R90F02.sp03,V4.5R90F02.sp04,V4.5R90F02.sp05

ADSM: V4.5R90F02.sp07

[Function Changes]

NONE

[Fixed Bugs]

Bug 196954: If the protected IP segment for an injection route has a prefix within the range of 48–64, traffic diversion may fail for certain IP addresses within the segment.

Bug 196995: A static MAC address cannot be added for an IPv6 address with a prefix smaller than 64 configured for an injection interface.

Bug 196749: Some country names involved in GeoIP rules are not translated into English.

[Notes]

None

- END -